


RECOVERY NOTES

PROPERTY CORNER INVESTIGATION

LOCATION



T. 6 S. R. 42 E
 Mer. _____ State Ore.
 Forest W.W. Dist. Union

LEGEND

- Corner searched-no evidence
- Corner or accessory found
- Corner marked by perm. mon.

DESCRIPTION OF FOUND CORNER

MATERIAL: LAVA ROCK SIZE: 17" x 2" x 8"
 HEIGHT ABOVE GROUND: 8" CONDITION: Good
 MARKINGS: 4 on west side of Rock

DESCRIPTION OF FOUND ACCESSORIES

D.F. 20" DOWN N25°E 37 LINKS
SEC 13
PP 30" S120W 31 LINKS
SEC 14

NOTE: Indicate full investigative details on back of form.

PHOTO IDENTIFICATION

Symbol & date UBM-0 8-7-60 Line or Roll 39-49 Exposure _____
 How Identified Pin Pointed Where filed U.R.S.

RECOVERED BY: ESP + H.F.E.

DATE: 6/16/63

TITLE: _____

Form R6-5680-180 (4/61)

HOW TO REACH CORNER

7100-52 (3/68)

USDA-FOREST SERVICE GPO 940-117
 Index File No. L-21
 T. 65 R. 42E

R.D. Union
 N.F. W-W
 State Ore.

CORNER RECORD (SEARCH)

Tract or Survey No. _____

Cor. No. _____

UNION COUNTY SURVEYOR

Date Received _____

Date Filed 12-23-87

By G. LANGLITZ, Deputy

File No. 402-87R

L-21