


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:
None.



See Survey 052-1994
Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

At postion established by survey:

Set a 2½" X 30" aluminum pipe with a 2½" aluminum cap, 26" in ground and surrounded with a mound of earth and stone.

Attached signs 54-2 & 54-9 to steel fence post, set 3.9 feet West of monument.

Set a steel fence post 3.1 feet South of monument.

New bearing trees established:

A 14" ponderosa pine bears N 56° E - 46.5 feet, scribed: E1/16S18BT.

A 13" ponderosa pine bears S 56° W - 37.5 feet, scribed: E1/16S19BT.

A fence corner bears S 18° E - 5.5 feet.

New bearing trees have a brass washer stamped 'PLS 1106' nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each bearing tree.

I hereby certify that the above corner monument was properly monumented to U.S.F.S standards by me on December 15, 1993.

Compass declination 18° East.

REGISTERED PROFESSIONAL LAND SURVEYOR

William R. Wells

OREGON JULY 22, 1977 WILLIAM R. WELLS 1106

Office of..... County of..... *Wenatche 12-31-94*
State of..... I hereby certify that the within instrument was filed in this office
for record on the..... day of.....

(COUNTY OFFICIAL)

(DEPUTY)

UNION COUNTY SURVEYOR
Date Received <i>11/3/94</i>
Date Filed <i>11/14/94</i>
By <i>Guy T. Clark</i>
File No. <i>155-1994R</i>