


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

0-4

History of original corner establishment:
None.



See Survey 052-1994

Description of corner evidence found:

A 13" douglas fir with blazes on four sides bears N58°W-23.0 feet.

Description of monument and accessories established to perpetuate the original location of this corner:

At postion established by survey:

Set a 2½" X 30" aluminum pipe with a 2½" aluminum cap, 24" in ground and surrounded with a mound of earth and stone.

Attached signs 54-2 & 54-9 to steel fence post, set 3.2 feet North of monument.

Set a steel fence post 3.0 feet West of the monument.

New bearing trees established:

A 16" douglas fir bears S 38° W - 4.6 feet, scribed: NE1/16S19BT.

A 14" douglas fir bears S 63° E - 23.9 feet, scribed: NE1/16S19BT.

New bearing trees have a brass washer stamped 'PLS 1106' nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each bearing tree.

I hereby certify that the above corner monument was properly monumented to U.S.F.S standards by me on December 29, 1993.

Compass declination 18° East.

REGISTERED PROFESSIONAL LAND SURVEYOR

William R. Wells

OREGON JULY 22, 1977 WILLIAM R. WELLS 1106

Renews 12-31-94

Office of..... County of.....

State of..... I hereby certify that the within instrument was filed in this office for record on the..... day of.....

(COUNTY OFFICIAL)

(DEPUTY)

UNION COUNTY	
SURVEYOR	
Date Received <u>4/3/84</u>	
Date Filed <u>11/14/84</u>	
By <u>Gregory T. Blawie</u>	
File No. <u>158-1994R</u>	