


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

R-4

History of original corner establishment:  
None.



See Survey 052-1994

Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

At postion established by survey:

Set a 2½" X 30" aluminum pipe with a 2½" aluminum cap, 22" in ground and surrounded with a mound of earth and stone.

Attached sign 54-9 & 54-2 to steel fence post, set 5.5 feet East of monument.

New bearing trees established:

A 21" ponderosa pine bears S 27° W - 51.9 feet, scribed: E1/16S30BT.

A 17" ponderosa pine bears N 13° E - 59.0 feet, scribed: E1/16S19BT.

New bearing trees have a brass washer stamped "PLS 1106" nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each bearing tree.

I hereby certify that the above corner monument was properly monumented to U.S.F.S standards by me on December 21, 1993.

Compass declination 18° East.

REGISTERED PROFESSIONAL LAND SURVEYOR
---

*William R. Wells*

OREGON JULY 22, 1977 WILLIAM R. WELLS 1106
---

*renews 12-31-94*

Office of..... County of.....

State of..... I hereby certify that the within instrument was filed in this office

for record on the..... day of..... 19.....

(COUNTY OFFICIAL)

<b>UNION COUNTY SURVEYOR</b>	
Date Received	<i>11/13/94</i>
Date Filed	<i>11/14/94</i>
By	<i>[Signature]</i>
File No.	<i>164-1994K</i>

(DEPUTY)

R-4