


Index File No. A 9
 T 25 R. 35E R.D. La Grande County Union Tract or Survey No. _____ Cor. No. _____
 Merid. Will. N.F. WW State Oregon



DESCRIBE CORNER MONUMENT FOUND
 Lodge pole pine 12" DBH
 good condition
 on uphill side of tree (scrubbing) 2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
 None found
 Possibly a 12" lodgepole (live)
 is a BT. 3

PHOTO IDENTIFICATION DATA
 Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature 7

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER 4

PLANE COORDINATE POSITION DATA
 State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Agency 8

Signature _____ Title _____ Division _____ Headquarters _____ Date _____ 7100-52 REV. 65 5

UNION COUNTY SURVEYOR

Date Received _____
 Date Filed 12-28-87
 By G. LANGRISH, DEPUTY
 File No. 468-87R

A-9