



- denotes Brass Cap set
- denotes 3/8 in iron pin set

**NOTES:**

Bearings are based on solar observations as recorded on survey for the U.S. Forest Service, sheet 2 of 2, by Krumbain Engineering, Ltd, dated July 31, 1979, Union County Survey Records.

Corners remonumented from evidence, found:

Southeast corner	Northwest corner
South 1/4 corner	Northeast corner
Southwest corner	East 1/4 corner

Corners set by proportionate method:

West 1/4 Corner	North 1/4 corner
-----------------	------------------

Center 1/4 corner set by intersection of North-South & East-West centerlines of Section 36.

Information on evidence, located for accessories found & set, are described in Certified Record of Land Monumentation, filed with the U.S. Forest Service & the Union County Surveyor.

*James V. Buisman*

<b>KRUMBEIN ENGINEERING CO.</b> ENGINEERS - SURVEYORS - PLANNERS 221 S. Main, Pendleton, Oregon	SCALE 1" = 500'
	DATE August 1, 1979
Survey for <b>BEN GROTE</b> Section 36, T4N, R38E, WM	DRN BY MH
	CKD BY J.H.B.
	DRNG NO. 79-52C

70-79