

## LOT LINE ADJUSTMENT

AN ADJUSTMENT OF THE LINE COMMON TO LOTS 20 AND 21 OF THE FINAL PLAT OF MOUNTAIN SOUND SECOND ADDITION RECORDED IN PLAT CABINET B-591 & 592 UNDER MICROFILM NUMBER 20005475. LOCATED IN GOVERNMENT LOT 1 OF SECTION 2 IN TOWNSHIP 4 SOUTH, RANGE 35 EAST OF THE WILLAMETTE MERIDIAN, UNION COUNTY, OREGON.

#### BASIS OF BEARINGS

NOU'56'50"E ALONG THE MOST WESTERLY LINE OF LOT 21 OF MOUNTAIN SOUND SECOND ADDITION AS SHOWN ON THE FINAL PLAT THEREOF RECORDED IN PLAT CABINET B-591 AND 592 UNDER MICROFILM NUMBER 20005475 IN THE OFFICIAL RECORDS OF UNION COUNTY, OREGON.



### REFERENCE MATERIAL

MOUNTAIN SOUND SECOND ADDITION RECORDED IN PLAT CABINET B-591 AND 592 UNDER MICROFILM NUMBER 20005475.

#### LEGEND

	ADJUSTED LOT LINE		
	EXISTING LOT LINE		
	SECTION OR SECTIONAL SUBDIVISION LINE		
	CENTERLINE		
	RIGHT-OF-WAY LINE		
	EASEMENT		
•	FOUND SURVEY MONUMENT AS NOTED.		
	FOUND 5/8" REBAR WITH A YELLOW PLASTIC CAP MARKING THE RIGHT OF WAY OF THE OF THE GRANDE RONDE RIVER RD.		
•	FOUND A 5/8" REBAR WITH A YELLOW PLASTIC CAP STAMPED "TOMKINS SURVEYING" PER THE FINAL PLAT OF MOUNTAIN SOUND SECOND ADDITION MICROFILM NO. 2005475, PLAT CABINET B—591 & 592.		
	SET A 5/8" X 30" IRON REBAR WITH A YELLOW PLASTIC CAP STAMPED "TOMKINS SURVEYING" ATTACHED.		
<b>+</b>	COMPUTED POSITION NOTHING FOUND OR SET.		
(X0X)	RECORD DIMENSION AS NOTED IF DIFFERENT THAN RECORD		
××××	FENCE		
	EDGE OF RIVER		

CURVE	ARC LENGTH	RADIUS	DELTA ANGLE	CHORD BEARING	CHORD LENGTH
C1	76.50'		2°20'16"	N22°04'58"E	76.49'
C2	33.17'	1969.86	0°57'53"	S21°19'21"W	33.17'
C3	253.60'	1874.86	7°45'00"	S19°22'35"W	253.41'

# 

UNION COUNTY
SURVEYOR

### NARRATIVE

THIS SURVEY WAS DONE AT THE REQUEST OF GREG TSIATSOS AND LES ANDERSON TO ADJUST THE LINE COMMON TO LOTS 20 AND 21 OF MOUNTAIN SOUND SECOND ADDITION AS SHOWN ON THE FINAL PLAT RECORDED IN PLAT CABINET B-591 & 592 UNDER MICROFILM NUMBER 20005475 TO FOLLOW THE EXISTING FENCE AS SHOWN. I HAVE PREPARED THE NECESSARY LEGAL DESCRIPTIONS FOR THE LOT LINE ADJUSTMENT WITH UNION COUNTY AND FIND NO UNUSUAL CONDITIONS ON THIS SURVEY OTHER THAN THE FENCE THAT IS BEING ADJUSTED TO.

THIS SURVEY WAS DONE USING TRIMBLE R6 GEODETIC GPS RECEIVERS USING REAL TIME KINEMATIC PROCEDURES WITH REDUNDANT MEASUREMENTS HAVING STANDARD ERRORS OF 8 MM + 1 PPM RMS.



RENEWS 12/31/15 /0//4/20/5



5 North Colville Street Walla Walla, WA 99362 509/956-3026 306/695-3488 509/547-5129 fax

Internet: www.hdjdesigngroup.com

	anni anni anni anni anni anni anni anni			
CLIENT: GREG TSIATS	os	PROJECT NO.: 3661-00		
SURVEYOR: GREG E. I	FLOWERS	DATE: OCTOBER 14, 2015		
CALC BY: GEF DRAWN BY		r: GEF	SCALE: 1"=100'	
SECTION: 2 TOWNSHIP:		4 SOUTH RANGE: 35 EAST		
CITY: STARKEY COUNTY: I		UNION	SHEET 1 OF 1	